


Daikin FTXC71B/RXC71B



?????????: ??? ????????????? ?????

??????? : Daikin FTXC71B/RXC71B

1154 €


????? ??? ??????? ??? ?? ???????

????????????Daikin

????????

???????????? Daikin_{FTXC71B/RXC71B} SENSIRA R-32

- [illegible]



????????????

❄️ ???? - BTU: 23.748

❄️ ???? - ?????????? ?????: A

SEER: 5.3

?????????? ???? M??????(mm): 1010/297/288
 ?????? ??????? ???? ????????: 60 dB

☀️ ???????? - BTU: 21.667

❄️ ???????? - ??????????? ??????: A++

❄ SCOP: 3.81

?????????? ?????. M??????(mm): 930/695/350
 ?????? ??????? ?????.????????: 69 dB

????? ???????

??? ?????? ????????????? ??? ?? ?????? ??????.