

Daikin FTXC60B/RXC60B



?????????????: ??? ?????????????? ??????


968 €

????? ???? ??????? ???? ?? ??????

????????????????? [Daikin](#)

??????????

????????????? Daikin FTXC60B/RXC60B SENSIRA R-32



?????????????????

⌘ ???? - BTU: 21.189

⌘ ???? - ?????????? ?????: A++

SEER: 6.4

?????????? ???. M??????(mm): 1010/297/288
?????? ???.?????? ???.???????: 60 dB

 ???? - BTU: 13.989

⌘ ??????? - ?????????? ???: A+

SCOP: 4.24

?????????? ???. M??????(mm): 845/615/300
?????? ???.?????? ???.???????: 66 dB

?????? ?????

???? ?????????? ?????????????? ??? ?? ?????? ?????.